

# Inspection Report

|                  |               |
|------------------|---------------|
| Report Number:   | INS-2026-2214 |
| Site:            | Kestrel House |
| Inspection Date: | 2026-03-12    |
| Inspector:       | I. Duarte     |
| Next Due:        | 2026-09-12    |

| Ref | Item               | Result | Observation             |
|-----|--------------------|--------|-------------------------|
| 1   | Fire alarm panel   | Pass   | No faults logged        |
| 2   | Emergency lighting | Pass   | All units tested        |
| 3   | Extinguishers      | Fail   | Unit 3B overdue service |
| 4   | Fire doors         | Pass   |                         |
| 5   | Escape routes      | Pass   | Clear throughout        |
| 6   | Signage            | Fail   | Missing on level 2      |
| 7   | Sprinkler valves   | Pass   |                         |
| 8   | Riser access       | Pass   | Key held at reception   |